



**US Army Corps
of Engineers®**

Fact Sheet **Site 47.9**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 47.9

Latitude/Longitude:

38.473375/-121.515865

Nearest Impact Area:

Clarksburg/West Sacramento

County: Yolo

Bank: Right

Type of Damage

Bank erosion

Length of Repair


1,031 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

U.S. Army Corps of Engineers



**For further information,
please contact:**

Stan Wallin
Project Manager
U.S. Army Corps of Engineers
(916) 557-5225

Stan.J.Wallin@spk01.usace.army.mil